

FORM HVOP

WARNING
(IMPORTANT NOTICE)

It is important that you check the **clearances** between the oil pump, crankshaft, connecting rods, and oil pan.

Also, make sure that the oil pick-up screen is not making contact with the oil pan.

Failure to insure proper clearances **voids** any warranty of this product.

REV. B

FRONT

FORM HVOP

PRECAUCION
(AVISO IMPORTANTE)

Es importante el checar los claros entre la bomba de aceite, cigüeñal, bielas y carter del aceite.

Igualmente, asegurarse de que el colador de aceite no haga contacto con el carter.

El no asegurarse de los claros apropiados *nulifica* cualquier garantía de este producto.

REV. B



BACK

NOTE!

ALSO USED AS PART OF THE FOLLOWING INSTRUCTION SHEETS:

- M55006 M79099
- M55031 M95021
- M66038 M98018
- M72027

SHEET SIZE - 4-1/4" x 5-1/2"
PAPER COLOR: YELLOW
PRINT FRONT & BACK

B	6/01/98	SPANISH SIDE ADDED	1882
A	2/16/89	(REVISED) COLOR WAS RED	1159
LTR.	DATE	REVISIONS	ECR #
MELLING TOOL COMPANY			
		ENGINE COMPONENTS PRODUCT ENGINEERING	
REF.	SHT.		OF
DRAWN BY	COMPLETED	CHECKED	APPROVED
MDB.	4/28/89	R G J	6-2-98
NAME			
SHEET-CAUTION INSTRUCTION			
PART NO.		HVOP	