


CAUTION

M87041
REV. D


This oil pump repair kit can rebuild oil pumps using either type of gasket, (steel ribbed .01 thick or paper .007 thick). However, be sure you replace the gasket with the same type of gasket you removed from the oil pump you're rebuilding. Failure to follow these instructions may result in low oil pressure or even engine failure.



FRONT

PRECAUCION

Este equipo de reparacion puede reconstruir bombas de aceite que empleen cualquier tipo de junta, (ribeteada de acero de 2,54 mm de grueso o de papel de 0,178 mm). Sin embargo, asegurese de reemplazar el mismo tipo de junta que se elimino de la bomba de aceite que esta reconstruyendo. El no seguir estas instrucciones puede dar pos resultado una baja presion de aceite e inclusive fallas del MOTOR.



BACK

SHEET SIZE - 3-1/2" x 5"
PAPER COLOR: YELLOW
PRINT FRONT AND BACK

D	3/25/03	CHANGED . TO , IN METRIC DIMS.	2688
C	3/25/03	CHANGED PRECAUCION TO PRECAUTION	2688
B	8/27/99	CONVERT TO METRIC	2205
A	9/22/98	SPANISH VERSION ADDED	1960
LTR.	DATE	REVISIONS	ECN #

MELLING TOOL COMPANY



ENGINE COMPONENTS
PRODUCT ENGINEERING



PROJ.	FORMS	SHT. 1 OF 1	
DRAWN BY	COMPLETED	CHECKED	APPROVED
KML	9/22/98	<i>[Signature]</i>	3/25/03
NAME		Full	
SHEET-CAUTION INSTRUCTION			
PART NO. M87041			