ORACLE
LIGHTING TECHNOLOGY

PAINTING INSTRUCTIONS

Materials Needed: Sandpaper, Cleaner, Fine-Line Tape, Paint.

1) Prepare the surface with 1500 grit Sandpaper.
2) Clean the surface with a pre-paint cleaner and lint free towel.
3) Now Mask the LED section off with 1/16" Fine-Line Masking Tape.
4) Using a thick blocking primer apply several light coats over the area.
5) Turn on the LED and see if the light is visible, if so add more primer.
6) Now add your color coats as directed by the paint manufacturer.
7) Remove the Fine-Line Masking Tape. Use razor blade if needed.
8) (Optional) For "Ghost" effect add one more light coat of color.
9) Now add your Clearcoat as directed by the paint manufacturer.
10) Allow the paint to fully cure before attempting installation.