
# INSTALLATION GUIDE

## #8985- 700R4 Braided TV Cable
## #8989- TH350 Braided TV Cable

**WARNING: SEVERE DAMAGE MAY OCCUR IF TV CABLE IS NOT PROPERLY INSTALLED AND ADJUSTED CORRECTLY**

Follow diagram below. Make certain the throttle valve cable moves freely, and installation is consistent with the measurements shown. It is **VERY** important that the cable operates within these parameters. Damage will occur if adjusted incorrectly.




**NOTE:** Check the cable regularly and replace it if the wire, or wire sheathing, show any signs of wear or damage. Operating the vehicle with a damaged cable could cause sticking or component failure, possibly resulting in personal injury or property damage.

12438 Putnam Street ● Whittier, CA 90602 ● tel (562) 921-0404 ● fax (562) 921-7515
website: www.hedman.com ● email: techsupport@hedman.com