



Part number SES1572TT

2016-2021 Honda Civic

SEDAN ONLY

10th Gen. 1.5L turbo 4cyl.

1- 4 piece cat back dual exhaust

1- triangle gasket (#12036)

2- 3.00 gasket (#17060)

1- 60mm gasket (#6064)

6- M10 hex bolt (#6038)

6- M10 hex nut (#6039)

2- Blue tips (#17210)



Complete kit:



Figure 2

Congratulations! You have just purchased the best engineered, dyno-proven exhaust system available.

Please check the contents of this box immediately.

Report any defective or missing parts to the Authorized Injen Technology dealer you purchased this product from.

Before installing any parts of this system, please read the instructions thoroughly. If you have any questions regarding installation please contact the dealer you purchased this product from.

Installation DOES require some mechanical skills. A qualified mechanic is always recommended.

*Do not attempt to install the intake system while the engine is hot. The installation may require removal of radiator fluid line that may be hot.

Injen Technology offers a limited lifetime warranty to the original purchaser against defects in materials and workmanship. Warranty claims must be handled through the dealer from which the item was purchased.

Injen Technology 244 Pioneer Place Pomona, CA 91768 USA

Please check the contents of this box immediately.

Parts and accessories are available on line at "Injenonline.com"

NOTE: All Injen exhaust systems are engineered to comply with the 95dB noise limit law specified by the California Highway Patrol and the Society of Automotive Engineers - Except ones that are designated for "Off-Road Use only".

Every Injen exhaust system is individually designed for a specific application and complies with the requirements of Sections 27150, 27151 & 27200 of the California Vehicle Code and Title 13 of the California code of Regulations, Section 10361, which establishes a noise limit of 95dB for passenger cars.

The age of your exhaust system along with certain engine modifications, such as headers, intake, etc., may also affect its current noise level output.

Please check with your local and state law enforcement agencies for exact regulation requirements.




Figure 3

Loosen the screws holding in the factory engine cover. This will allow to loosen screws on pipe.




Figure 4

Loosen the 3 nuts holding in the pipe using 14 mm socket with wrench. Save these 3 nuts for later install.




Figure 5

With lubrication, remove all the exhaust hangers from the rubber isolation mounts.




Figure 6

Continue to remove all hangars from the exhaust system.



Figure 7

Carefully position and slide back and remove the exhaust out of the vehicle.




Figure 8

Remove the isolation mount from the exhaust closest to the 3 hole flange. Re-install to the new engine exhaust for easier installation.




Figure 9

With provided 3 hole gasket, Install the front pipe to the 3 hole flange. Secure using original nuts from step 4.



Figure 10

Now install the mid-pipe to the exhaust. Secure using provided 3" gasket and bolts with nuts.



Figure 11

Install the rear sections, passenger side and driver side. Secure using provided M10 bolts and nuts with correct gasket. Do not tighten.




Figure 12

Position all the hangars to to the isolation mounts. Position and adjust fitment. Do not tighten.




Figure 13

Position for best fit and clearance. Once the exhaust is in correct position, Secure and tighten.



Figure 14

Congratulations! You have just completed the installation of this exhaust system. Verify and adjust the rear section of the exhaust, make sure muffler and tip do not touch any plastics or it can melt. Periodically, check the alignment of the exhaust, normal wear and tear can cause nuts and bolts to come loose. **Note: Check clearance and adjust if needed! Failure to check the alignment and adjust the exhaust can cause damage that will void the warranty. Injen Technology is not responsible for any damages caused by/from improper installation.**