



17491 Apex Cir.  
 Huntington Beach, CA 92647  
 Phone: 714-848-5515  
 Toll Free: 800-535-1161  
 Fax: 714-847-6290  
[sales@powerbyjet.com](mailto:sales@powerbyjet.com)  
[www.jetchip.com](http://www.jetchip.com)

## 2 NEW Mass Air Sensors # 69160 & 69161

The sensors are a simple bolt on replacement for the stock unit and uses the factory intake housing with no other vehicle modifications required. Compatible with other performance upgrades such as cold air intakes, exhaust, computer upgrades, etc.  
Up to 13 more hp over stock mass air sensor and Improved Mileage.



### APPLICATIONS

Year	Make	Model	Engine	Part #
2012-2014	Scion	IQ, TC, XD	1.3, 2.5	69160
2010-2014	Toyota	4runner	4.0	69160
2013-2014	Toyota	Avalon	2.5, 3.5	69160
2012-2014	Toyota	Camry	2.5, 3.5	69160
2009-2014	Toyota	Corolla	1.8	69160
2009-2014	Toyota	FJ Cruiser	4.0	69160
2010-2014	Toyota	Highlander	2.7, 3.5	69160
2009-2014	Toyota	Matrix	1.8	69160
2013-2014	Toyota	RAV4	2.5	69160
2011-2014	Toyota	Sienna	2.7, 3.5	69160
2010-2014	Toyota	Tundra	4.0	69160
1996-1998	Buick	LeSabre, Park Ave, Regal, Riviera	3.8L	69161
1996-1998	Chevrolet	Camaro	3.8L	69161
1998	Chevrolet	Lumina, Monte Carlo	3.8L	69161
1996-1998	Oldsmobile	98, Aurora, Delta 88, LSS	3.8L	69161
1998	Oldsmobile	Intrigue	3.8L	69161
1996-1998	Pontiac	Bonneville, Firebird, Grand Prix	3.8L	69161

69160 Jobber \$158.96 UPC 064330044264  
 69161 Jobber \$149.96 UPC 064330044288