

M55031
REV. C

WARNING
IMPORTANT NOTICE

A NEW INTERMEDIATE SHAFT with a PINNED STEEL SLEEVE MUST be used with this Oil Pump Application. DO NOT use a substitute.

If the STEEL SLEEVE is not used the driveshaft of the Oil Pump can be damaged, resulting in failure of the pump. Failure to follow this warning VOIDS any warranty to this product.

FRONT

PRECAUCION
NOTA IMPORTANTE

Una nueva flecha intermedia con camisa con espiga debe de usarse con esta bomba de aceite. No usar un sustituto.

Si no se usa la camisa de acero, la flecha de la bomba de aceite puede danarse, resultando falla de la bomba. El no seguir estas instrucciones CANCELA cualquier garantia de este producto.

BACK

SHEET SIZE - 4-1/4" x 5"
PAPER COLOR: YELLOW
PRINT FRONT & BACK

C	3/25/03	CHANGED FLECA TO FLECHA	2688
B	7/19/99	SPANISH VERSION ADDED	2177
A	11/7/90	BACK ADDED (HVOP)	1316
LTR. DATE		REVISIONS	ECR #

MELLING TOOL COMPANY



ENGINE COMPONENTS
PRODUCT ENGINEERING



REF.	SHT. 1 OF 1			
DRAWN BY	COMPLETED	CHECKED	APPROVED	SCALE
G.A.	11/7/90	<i>[Signature]</i>	3/25/03	FULL
NAME	SHEET-CAUTION INSTRUCTION			
PART NO.	M55031			