


MT1023
REV. A

The enclosed chain may not have the timing links identified. To mark these links, lay chain flat and straight. Mark a side bar link, count over 42 side bar links and mark the following link as shown.



FOR ALL NISSAN ENGINES LISTED BELOW
L16, L18, L24, L24E, L28E AND L28ET