

IMPORTANT INSTRUCTIONS

3-10-2016

MT1045

Ford's updated the primary timing chain tensioner. The tensioner in this set may be different than the part being removed from the engine. The old tensioner was manufactured with a cast iron housing. The new tensioner has an aluminum housing.

Melling Engine Parts

WWW.MELLING.COM

Rev. A