

FORM HVOP

## WARNING ( IMPORTANT NOTICE )

It is important that you check the **clearances** between the oil pump, crankshaft, connecting rods, and oil pan.

Also, make sure that the oil pick-up screen is not making contact with the oil pan.

Failure to insure proper clearances **voids** any warranty of this product.

REV. A



SHEET SIZE : 4 1/4" x 5"

SHEET COLOR : YELLOW

**NOTE!**

ALSO USED AS PART OF THE FOLLOWING INSTRUCTION SHEETS:

M55006    M79099  
M55031    M95021  
M66038    M98018  
M72027

|  |           |  |   |       |
|--|-----------|--|---|-------|
| A  | 2/16/89   | (REVISED)                                | COLOR WAS RED   | 1159  |
| LTR.   | DATE      | REVISIONS                                | ECR #   |       |
| <b>MELLING TOOL COMPANY</b>  |           |  |   |       |
|  |           | ENGINE COMPONENTS<br>PRODUCT ENGINEERING |  |       |
| REF.   | SHT.      |  | OF  |       |
| DRAWN BY   | COMPLETED | CHECKED                                  | APPROVED  | SCALE |
| MDB.   | 2/16/89   | RGJ                                      | 2-18-89   |       |
| NAME   |           |  |   |       |
| SHEET-CAUTION INSTRUCTION  |           |  |   |       |
| PART NO.   |           | HVOP                                     |   |       |