


CAUTION

M81046

THESE INSTRUCTIONS MUST BE FOLLOWED IN ORDER FOR PROPER INSTALLATION OF THE K-81A KIT.

UTILIZE INCLUDED GASKET IF PUMP TO BE REBUILT CONTAINS A GASKET. IF PUMP TO BE REBUILT DOES NOT CONTAIN A GASKET, THE GASKET INCLUDED IN THE REBUILD KIT IS NOT TO BE INSTALLED.




FRONT

PRECAUCION



ESTAS INSTRUCCIONES DEBEN DE SEGUIRSE PARA LA ADECUADA INSTALACION DEL KIT DE REPARACION K-81A.

USAR LA JUNTA INCLUIDA SI LA BOMBA A REPARAR TENIA UNA JUNTA. SI LA BOMBA A REPARAR NO CONTENIA UNA JUNTA. LA JUNTA INCLUIDA EN ESTE KIT NO DEBE DE INSTALARSE.



BACK

SHEET SIZE = 4.75 x 3.25
 SHEET COLOR = WHITE
 PRINT FRONT & BACK

1/3/00		RELEASED		2267
LTR.	DATE	REVISIONS	ECR #	
MELLING TOOL COMPANY				
		ENGINE COMPONENTS PRODUCT ENGINEERING		
				
PROJ. M-81		SHT. 1 OF 1		
DRAWN BY	COMPLETED	CHECKED	APPROVED	SCALE
KML	1/3/00	1/3/00	scm	2/28/00
NAME				
SHEET-CAUTION INSTRUCTION				
PART NO. M81046				